

WSU HIBAL

Launch Go/No-Go Conditions

Last Updated 2/4/2009

- Visibility must be greater than 5 miles
- Dry conditions (no rain, mist, or high humidity)
- Temperature must not be excessively cold (less than 20° F)
- Ground wind speeds must be below 20 mph bursts
- Experienced advisor must be present at all launches
- Equipment must be thoroughly tested and inspected by advisors
- Balloon must not be projected to land in or travel through/near restricted air space
- Payload must not be projected to land more than 90 miles from Dayton
- Payload must be ready Wednesday before launch